

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 61550
Tel: 815-692-2929



September 18, 1998

JMHLTR: #98-0245

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Dresden Nuclear Power Station Unit 2
Fuel Bundle Movement permitted during Control Room Ventilation outage
due to programmatic failures within the Work Planning and Execution
Process
Licensee Event Report 1998-012-00
NRC Docket Number 50-237

The enclosed Licensee Event Report, which is a final report, describes movement of irradiated fuel bundle while control room refrigeration unit was inoperable. This condition is being reported pursuant to 10 CFR 50.73(a)(2)(i)(B) which requires the reporting of any operation or condition prohibited by the plant's Technical Specification.

The following actions were taken:

Operations Policy #13 revised to include performance of a collegial review of emergent work. (Complete)

Scheduling process revised to indicate mode changes on the Site Integrated Schedule. (Complete)

The Shift Operations Supervisor has set forth expectations for listing "compensatory actions" on LCO Board located in Control Room. This information has been distributed through the Daily Orders and an Operations Memo. (Complete)

Operations has matrixed the Technical Specifications, capturing where single systems cross multiple Tech Spec sections. (Complete)

Technical Specification retraining is being performed for all SRO-L and Licensed Operators. (Complete)

9809240364 980918
PDR ADOCK 05000237
S PDR

//
JE22


This correspondence contains the following commitment(s):

A review of Fuel Handling procedures will be performed to determine those requiring identification of Technical Specification LCOs . (2371809801201)

A review of plant procedures will be performed to determine those requiring identification of Tech Specs. (2371809801202)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,



J. M. Hefley
Site Vice President
Dresden Station

Enclosure

cc: Regional Administrator, Region III
 NRC Resident Inspector's Office