



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

July 10, 2017
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. William Ward
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-17-0131L

Subject: Revised Response to RAI 334-8373 for the Question 03.12-16 (Rev.2)

References: 1) NRC Request for Additional Information 334-8373, dated December 14, 2015
2) KHNP Letter MKD/NW-16-0712L, Response to RAI 334-8373 for Question 03.12-16, dated June 30, 2016
3) KHNP Letter MKD/NW-16-0909L, Revised Response to RAI 334-8373 for the Question 03.12-16, dated August 19, 2016

KHNP is hereby submitting the response to RAI 334-8373, dated December 14, 2015. The revised response addresses Question 03.12-16 to clarify the loading combinations for piping supports. The enclosure contains the revised response to RAI 334-8373 (Rev.2) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Han-gon Kim
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro & Nuclear Power Co., Ltd.

Enclosure: Revised Response to RAI 334-8373 for the Question 03.12-16 (Rev.2) (Non-Proprietary)

Enclosure

Revised Response to RAI 334-8373 for the Question 03.12-16 (Rev.2)

(Non-Proprietary)

July 10, 2017