

UNSEEN EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 8 9 I L D R S 2 14 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5 57 CAT 58

CON'T

0 1 8 9 REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 1 1 9 8 0 8 0 3 2 4 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, two successive samples of "A" waste sample tank showed a

0 3 curie content of 1.5 Ci and 0.9 Ci, exceeding the 0.7 Ci limit of T.S. 3.8.d. There

0 4 was no release of activity and no public health hazard occurred. This event had

0 5 occurred before (R.O. 79-43/03L-0 Docket 050-237).

0 6

0 7

0 8

0 9 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

M A 11 D 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16

9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

8 0 0 0 6 / 0 3 X 1

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

G 18 Z 19 Z 20 0 0 0 0 0 22 N 23 N 24 Z 25 Z 9 9 9 9 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The high-activity in "A" Waste Sample Tank came from "C" clean up demin. bed. This

1 1 bed was to be placed into service and was flushed. The flushing water was sent to

1 2 the rad. waste collector tank and then processed to "A" waste sample tank. Tank "A"

1 3 was reprocessed to an underground tank within 24 hours as required by Tech. Specs.

1 4 Procedure is being changed to include sampling at the collector.

1 5 8 9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32

F 28 0 1 4 29 N/A A 31 Activity Analysis of Tank

8 9 10 12 13 44 45 46 80

1 6 8 9 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

Z 33 Z 34 N/A N/A

8 9 10 11 44 45 80

1 7 8 9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39

0 0 0 37 Z 38 N/A

8 9 11 12 13 80

1 8 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41

0 0 0 40 N/A

8 9 11 12 80

1 9 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43

Z 42 N/A

8 9 10 80

2 0 8 9 PUBLICITY ISSUED DESCRIPTION 45

N 44 N/A

8 9 10 80

8004140429

Sam Bader

68 69 80

NRC USE ONLY

X-489

Hannell  
Jones  
Roisman

11