



Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

DISTRIBUTION SERVICES UNIT

1980 NOV 24 PM 2 37

November 12, 1980

US NRC
 DISTRIBUTION SERVICES
 BRANCH

DJS Ltr. #80-240

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Reportable Occurrence Report #80-42/03L-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

Douglas J. Scott

D. J. Scott
 Station Superintendent
 Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U.S. NRC, Document Management Branch
 File/NRC

A002
 S
 1/1

5
 8011250529