



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

February 5, 1981

Mr. Dennis M. Crutchfield, Chief  
 Operating Reactors Branch #5  
 Division of Licensing  
 U.S. Nuclear Regulatory Commission  
 Washington D.C. 20555

Subject: Dresden 2  
 SEP Topic VI-7.A.3, ECCS Actuation System  
 NRC Docket 50-237

Dear Mr. Crutchfield:

Since your letter of December 15, 1980 to J.S. Abel requesting additional information concerning the minimum flow bypass control for each ECCS pump, the NRC Staff, EG&G Idaho and Edison personnel have had discussions concerning the need for testing the valves. The results of those discussions are documented in R.F. Janecek's January 16, 1981 letter to T.A. Ippolito.

If you require additional information concerning your request for information or if you have any questions concerning this matter, please contact this office.

One (1) signed original and thirty-nine (39) copies of this transmittal are provided for your use.

Very truly yours,

*Robert F. Janecek*

Robert F. Janecek  
 Nuclear Licensing  
 Administrator  
 Boiling Water Reactors

RECEIVED DISTRIBUTION SERVICES UNIT

1981 FEB 17 AM 9 44

U.S. NRC  
 DISTRIBUTION SERVICES  
 BRANCH

A035  
 3  
 1/0

NPS:mnh  
 0389B  
 cc: RIII Inspector, Dresden

P 8102170301