



Telegram

VEC315 (2253) (1-047409C084) PD 03/25/74 2251

1974 APR 25 PM

ICS IPMVEIB MVN

02136 TDVE MORRIS IL 106 03-25 245P CDT

PMS MR JAMES F KEPPLER

TELEGRAMS (OTHER THAN MONEY ORDERS)

REGIOIANL DIRECTOR DIRECTORIAL LEAD DEREGULATORY OPERATION (ES-AGENT. NO-ADDRESS)

REGEN 3 US ATOMIC ENERGY COMMISSION

312-858-2660

799 ROOSEVELT ROAD

date dtd 3/27

10:30 A

RDC By hp

GLENELLEN IL 60137

to be mailed or filed

mail

attempts to deliver (Indicate DA or BY)

SUBJECT EPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2. THIS WILL CONFIRM A CONVERSATION WITH FRED MAURA OF YOUR OFFICE AT 1330 HOURS THIS DATE CONCERNING FAILURE OF TURBINE CONTROL VALVE #1 TO PRODUCE A GENERATOR LOAD REJECTION TRIP ON B SAFETY SYSTEM WHILE PERFORMING NORMAL TURBINE WEEKLY TURBINE SURVEILLANCE AT 0530 3-23-74 THE

INSTRUMENT CHANNEL WAS IMMEDIATELY TRIPPED BY PULLING A FUSE IN THE

SF-1201 (R5-69)



Telegram

TRIP SYSTEM LOGIC.

LOAD WAS REDUCED BELOW THE 40 PERCENT BY-PASS CAPACITY AND REPAIRS INITIATED ON WHAT WAS FOUND AT AN IMPROPERLY POSITIONED MICRO SWITCH THIS NOTIFICATION WILL BE FOLLOWED WITH A 10 DAY REPORT

B B STEPHENSON

SUPERINTENDANT DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

ROUTE 1 MORRIS ILLINOIS

NNNN

APR 1 1974

8103030147

SF-1201 (R5-69)

008

1974 MAR 25 PM 11 26

USAEC HQS GTWN

WU WSH

50-237

U.S. ATOMIC ENERGY COMM.  
TWX UNIT

TLXAC04 WAF251(2253)(1-047409C084002)PD 03/25/74 2251

ICS IPMVEIB MVN


2137 TDVE MORRIS IL 106 03-25 245P CDT

PMS MR J F O'LEARY

DIRECTOR DIRECTORATE OF LICENSING

U S ATOMIC ENERGY COMMISSION

WASHINGTON DC 20547



SUBJECT EPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2. THIS WILL CONFIRM A CONVERSATION WITH FRED MAURA OF YOUR OFFICE AT 1330 HOURS THIS DATE CONCERNING FAILURE OF TURBINE CONTROL VALVE #1 TO PRODUCE A GENERATOR LOAD REJECTION TRIP ON B SAFETY SYSTEM WHILE PERFORMING NORMAL TURBINE WEEKLY TURBINE SURVEILLANCE AT 0530 3-23-74 THE

INSTRUMENT CHANNEL WAS IMMEDIATELY TRIPPED BY PULLING A FUSE IN THE TRIP SYSTEM LOGIC.

LOAD WAS REDUCED BELOW THE 40 PERCENT BY-PASS CAPACITY AND REPAIRS INITIATED ON WHAT WAS FOUND AT AN IMPROPERLY POSITIONED MICRO SWITCH THIS NOTIFICATION WILL BE FOLLOWED WITH A 10 DAY REPORT

B B STEPHENSON

SUPERINTENDANT DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY


ROUTE 1 MORRIS ILLINOIS

NNNN

1120P EDT  
USAEC HQS GTWN

WU WSH

*Dune*  
8103030147



2560