

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

Incident Notification From: Commonwealth Edison Company 50-237  
(Licensee & Docket No. (or License No.))

Transmittal Date: June 18, 1976 Dresden Station-Unit #2

Distribution:

IE Chief, FOSB  
IE Chief, FC&EB  
IE:HQ(4)  
Licensing(4)  
DR Central Files  
IE Files

Distribution:

IE Chief, FOSB  
IE Chief, FC&EB  
IE:HQ(4)  
L:D/D for Fuels & Materials  
DR Central Files  
IE Files

Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

TELETYPE UNIT: 110-110  
Telecop or Telegraphed GE 6-16-76  
7:30 p.m.  
DC \_\_\_\_\_  
By KC

cc:  
Director  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

SUBJECT: DPR-19, Dresden Nuclear Power Station, Unit 2.

This will confirm a conversation with Mr. D. Knopf of your office at 3:09 p hrs this date concerning instrument drift on 2 instruments. P.S. 2-263-55A & P.S. 2-263-55C (Reactor Hi. pressure scram switches) these switches had drifted 2 # above the Tech spec limit. These drifts were found on the monthly surveillance for these instruments.

*Arthur M. Roberts*

\*\*\*\*\*  
To Call:  
GE - 7-858-2660x16  
DC - 9-1-301-492-7617 (auto)  
WU - 815-942-4449/4321  
Station Dist: Originator (copy)  
Incident File (copy)  
Telegram File (orig)

E. B. Stephenson, Superintendent  
Dresden Nuclear Power Station  
Commonwealth Edison Company  
R.R. #1  
Morris, IL 60450  
Telephone: 815-942-2920/2921x212  
(telecopy x262)

Rev. 12-75

6/16/76  
Rec'd 342

8103100129