

SHT HSB  
41981E149 05/29/74  
CS IPMBNGZ CSP  
3122422734 MGM TDBN MORRIS IL 100 05-29 0619P EDT  
ZIP 20545

**western union Mailgram**





J F OLEARY DIRECTOR  
DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION  
WASHINGTON DC 20545

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT TWO THIS WILL CONFIRM A CONVERSATION WITH MR W FISHER OF YOUR OFFICE AT 1610 HOURS THIS DATE CONCERNING ACTIVITY LEVELS IN AN ABOVE GROUND STORAGE TANK IN EXCESS OF 0.7 CURIES AS REQUIRED BY SECTION 3.8.D OF THE TECHNICAL SPECIFICATIONS THE TANK WERE NOT REPROCESSED TO A BELOW GROUND STORAGE TANK WITHIN 24 HOURS THE A WASTE SAMPLE TANK CONTAINED 1.04 CURIES WHEN FILLED AT 1504 HOURS ON 5-27-74 DUE TO INABILITY TO REPROCESS THIS WATER DUE TO IMPROPER FILTER PERFORMANCE IT WAS THEN TRANSFERED TO ANOTHER ABOVE GROUND TANK IE THE WASTE SURGE TANK WHICH ADDITIONALLY EXCEEDED LIMITS (1.04 CURIES) EFFORTS ARE PRESENTLY IN PROGRESS TO IMPROVE FILTERING PERFORMANCE FURTHER INFORMATION WILL FOLLOW IN A TEN DAY REPORT  
B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION  
COMMONWEALTH EDISON CO RURAL ROUTE 1 MORRIS ILLINOIS 60450

18119 EDT

MGMWSHT HSB



8103110518

REGULATORY DOCKET FILE COPY

4816

WESTERN UNION INCOMING

008

1974 MAY 29 PM 7 39

U.S. ATOMIC ENERGY COMMISSION  
T.W.X UNIT

50-237

USAEC HQS GTWN  
WU WSH

TLXA171 WAG223(1818)(2-041927E149)PD 05/29/74 1818

ICS IPMBNGZ CSP

3122422734 TDBN MORRIS IL 128 05-29 0618P EDT



~~PMS J.F. O'LEARY DIRECTOR, EONE DUPLICATE~~  
DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION  
WASHINGTON DC 20545

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT TWO THIS WILL  
CONFIRM A CONVERSATION WITH MR W FISHER OF YOUR OFFICE AT 1610  
HOURS THIS DATE CONCERNING ACTIVITY LEVELS IN AN ABOVE GROUND  
STORAGE TANK IN EXCESS OF 0.7 CURIES AS REQUIRED BY SECTION  
3.8.D OF THE TECHNICAL SPECIFICATIONS THE TANK WERE NOT REPROCESSED  
TO A BELOW GROUND STORAGE TANK WITHIN 24 HOURS THE A WASTE SAMPLE  
TANK CONTAINED 1.04 CURIES WHEN FILLED AT 1504 HOURS ON 5-27-74  
DUE TO INABILITY TO REPROCESS THIS WATER DUE TO IMPROPER FILTER  
PERFORMANCE IT WAS THEN TRANSFERED TO ANOTHER ABOVE GROUND TANK  
IE THE WASTE SURGE TANK WHICH ADDITIONALLY EXCEEDED LIMITS (1.04  
CURIES) EFFORTS ARE PRESENTLY IN PROGRESS TO IMPROVE FILTERING  
PROFORMANCE FURTHER INFORMATION WILL FOLLOW IN A TEN DAY REPORT  
B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION  
COMMONWEALTH EDISON CO RURAL ROUTE 1 MORRIS ILLINOIS 60450

NNNN

MAY 29 651P EDT\*

USAEC HQS GTWN  
WU WSH



REGULATORY DOCKET FILE COPY C: 4815  
WESTERN UNION INCOMING