

## deciem

VEA250(1724)(1-028860C338)PD 12/04/73 1721

1973 DEC -4 PH 4: 25

ICS IPMVEIC MVN

03151 TDVE MORRIS IL 107 12-04 355PM CST

J. J.

PMS MR JAMES G. KEPPLER

TELEGRAMS (OT: Is PhitciCAL DLLIVERY req ested?

REGIONAL DIRECTOR. DIRECTORA BODF REGULATORY OPERATIONS

REGION 3, US ATOMIC ENERGY COMMISSION, AUX

Date SSION, WOX

75-4

799 ROOSEVELT ROAD GLENELLYN IL 60137

Attempts to deliver (Indicate DA or BY)

SUBJECT DPR 19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1505 HOURS THIS DATE CONCERNING UNIT 2 TORUS HIGH LEVEL CONDITION CAUSED BY DRAIN FROM HPCI DRAIN LINE GOING TO TORUS. WHILE MAINTANANCE PATCHED STEAM DRAIN LINE TO CONDENSOR, HPCI STEAM DRAINS WERE LINED UP TO TORUS. OPERATIONS FAILED TO GET THE REPORT THAT REPAIRS WHERE COMPLETE, AND FAILED TO NOTICE GRADUAL RISE IN TORUS LEVELS UNTIL ALARM SOUNDED BEYOND LIMITS AT 0715 TODAY. LINE WAS

SF-1201 (R5-69)





1973 DEC -4 PH 4: 25

RESTORED TO NORMAL ON HPCI DRAIN AND TORUS LEVEL PUMPED DOWN TO NORMAL LEVEL AT 0900.

W T WORDEN, SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH EDISON COMPANY RR 1 MORRIS ILLIAUIS

NNNN

8103120478

DEC 7 1972

shore.