

VEC368(1710) (1-029190C260) PD 09/17/73 17081973 SEP 17 PM 5: 23

ICS IPMVEIC MVN

0172

03181 TDVE MORRIS ILL 115 09-17 338P CDT

PMS BOYGE GRIER

DIRECTOR DIVISION OF COMPLIANCE REGION 3 US ATOMIC ENERGY COMMISSIO

MUX 799 ROOSEVELT RD

GLEN ELLYN ILL 60137

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL

CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1435 HOURS

THIS DATE CONCERNING FAILURE MO-2-220-2. VALVE WAS APPARENTLY

TIMED SUCCESSFULLY ON 16-24 SHIFT 14 SEPTEMBER 1973. ABOUT 1200

ON SEPTEMBER 15 OPERATOR ATTEMPTED TO OPEN THE VALVE, BUT TH

E

BREAKER TRIPPED. SUBSEQUENT INVESTIGATION REVEALED THAT THE VALVE

WAS IN FACT OPEN ALTHOUGH IT INDICATED SHUT. DISASSEMBLY OF THE VALVE

REVEALED A COTTER PIN WAS MISSING. THIS PREVENTED SHAFT

OVER

SF-1201 (R5-69)

Rec'd 9-20-73

1973 SEP 17 PM 5: 23

FROM DRIVING VALVE CLOSED. UNIT WAS SHUT DOWN AT THE TIME VALVE
PROBLEM WAS DISCOVERED, START UP WAS DELAYED UNTIL REPAIRS COMPLETE
AND TESTED SATISFACTORILY.

W P WORDEN, SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

RURAL ROUTE 1

MORRIS ILLINOIS

TELEGRAMS (OTHER THAN MONEY ORDERS)

Is PHYSICAL DELIVERY requested? _____ (YES-AGENT, NO-ADDRESSEE)

AGENT SECTION ADDRESSSEE SECTION

Nbr. & Name _____ Nbr. 312-858-2660

Date dtd 9-18-73 Time dtd 1042A To BC By KR

To be mailed or filed Mail

Attempts to deliver (Indicate DA or BY)

SF-1201 (R5-69)

[Handwritten scribble]

8103120826