



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

*DSB*

May 4, 1981

DJS LTR #81-365

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #81-18/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment.

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Mgt. Branch  
File/NRC

8105140220  
S

MAY 11 1981