



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

February 15, 1984

Mr. Don Chery
 Project Manager
 Integrated Assessment
 Division of Licensing
 U.S. Nuclear Regulatory Commission
 Washington D.C. 20555

Subject: Dresden 2 - SEP Integrated Assessment
Topic VII-1.A, Isolation of Reactor Protection
System from Non-Safety Systems, Including
Qualification of Isolation Devices
NRC-Docket 50-237

- (a) Resubmittal of Response
- (b) Attachment: Letter, R.F. Janecek to G.C. Lainas dated January 22, 1981.

Dear Mr. Chery:

During a recent conversation with Mr. Ray Scholl (NRC) it became evident that page 2 was missing from our response to the subject topic. By this letter I am resubmitting a complete copy of the response.

Also, Mr. Scholl requested a copy of The Janecek (CECo) to Lainas (NRC) Letter dated January 22, 1981. This letter provided a response to Mr. Lainas' request for additional information concerning the isolation of Dresden's Reactor Protection System (Letter: G.C. Lainas to J.S. Abel, October 22, 1980).

Please address any questions you may have concerning this matter to this office.

Sincerely,

Bob Rybak
 Nuclear Licensing Administrator
 Boiling Water Reactors

50-237

DSS:mnh/4116D
 Attachment
 cc: W/A RIII Resident Inspector, Dresden Station
 File 2.12.2.74.F.1.a

8403090185 840215
 PDR ADOCK 05000237
 P PDR

A035
 1/1