



Commonwealth Edison

One First National Plaza, Chicago, Illinois

Address Reply to: Post Office Box 767

Chicago, Illinois 60690

FE01

October 18, 1985

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Dresden Station Units 2 and 3
Response to Inspection Report Nos.
50-237/85-029 and 50-249/85-024
NRC Docket Nos. 50-237 and 50-249

Reference (a): Letter from L. A. Reyes to Cordell Reed
dated September 18, 1985.

Dear Mr. Keppler:

This letter is in response to the inspection conducted by Messrs. R. Smeenge and R. Sutphin on August 15, August 19-28, and September 3, 1985, of activities at Dresden Station. Reference (a) identified certain activities appeared to be in noncompliance with NRC requirements. The Commonwealth Edison Company's response to the Notice of Violation is provided in the enclosure.

If you have any further questions regarding this matter, please direct them to this office.

Very truly yours,

M.S. Jurbok
for D. L. Farrar
Director of Nuclear Licensing

lm

Attachment

8510250231 851018
PDR ADOCK 05000237
Q PDR

cc: NRC Resident Inspector - Dresden

11.
OCT 21 1985

0785K

ATTACHMENT

COMMONWEALTH EDISON COMPANY

RESPONSE TO NOTICE OF VIOLATION

As a result of the inspection conducted on August 15, August 19-28, and September 3, 1985, the following violation was identified:

10 CFR 50, Appendix B, Criterion II, as implemented by the Commonwealth Edison Company (CECo) Topical Report CE-1-A requires that indoctrination and training of personnel performing activities affecting quality be accomplished as necessary to ensure that suitable proficiency is achieved and maintained.

Contrary to the above, the licensee failed to provide for the indoctrination and training of plant personnel relative to Quality Assurance Manual revisions within the time period specified by Procedure No. QP 2-52.

CORRECTIVE ACTIONS TAKEN

All personnel who were required to receive the training on the June 5, 1985 Quality Assurance revision but were delinquent have now been trained.

CORRECTIVE ACTION TAKEN TO AVOID FURTHER NONCOMPLIANCE

In order to avoid any delays beyond the 60-day training requirement for future revisions, the Training Department will track the completion of individual departmental training more closely. The Training Department will issue reminder memos on an increased frequency during the course of the 60 day period. These reminders will be issued to the respective department head early in the time frame and will receive progressively wider distribution culminating with the Station Manager. The Training Department has also required that dates be added next to each individual's signature to indicate when the training was accomplished as well as making the due date more obvious to each department head on a new form attached to the training package.

In addition, if the person has not completed the required training on or before the due date, their security badge will be pulled on the first working day after the due date and held until the training is completed or an evaluation made as to the applicability of the required training.

DATE WHEN FULL COMPLIANCE WILL BE ACHIEVED

Full compliance has been achieved as of October 17, 1985