

UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: 526-4597


JUL 15 1968

J. P. O'Reilly, Chief, Reactor
Inspection and Enforcement Branch
Division of Compliance, Headquarters

DUKE POWER COMPANY, OCONEE UNITS 1, 2, 3
LICENSE NOS. CPPR-33, 34, 35, DOCKET NOS. 50-269, 270, 287

Transmitted herewith for information are copies of CO Report
Nos. 269/68-3, 270/68-3, and 287/68-3, covering the visit of
June 19-21.

Please note that two items of nonconformance are described in
the report. Satisfactory corrective action was taken by the
licensee at the time of the inspection. No further Region II
action is therefore planned on the two items.


F. J. Long
Senior Reactor Inspector

CO:II:FJL

Enclosure:

Rpt Nos. 269/68-3,
270/68-3, 287/68-3

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
R. W. Kirkman, CO:I
B. H. Grier, CO:III
D. I. Walker, CO:IV
R. W. Smith, CO:V

→ REG Files

7911180075

ML 15203A692