



UNITED STATES
ATOMIC ENERGY COMMISSION
 DIVISION OF COMPLIANCE, REGION IV
 10395 WEST COLFAX, ROOM 200
 DENVER, COLORADO 80215

November 5, 1969

J. P. O'Reilly, Chief
 Reactor Inspection and Enforcement Branch
 Division of Compliance, Headquarters

ADDITIONAL INFORMATION ON CADWELDS

Attached is a recent memorandum from Mr. Crews to me which relates the information on Cadwelds that he obtained during a visit to the Rancho Seco construction site. Part of this information was contained in my memorandum to you of October 28. Mr. Crews has included the latest instructions for making Cadweld splices that are being provided by the manufacturer, Erico Products, Inc. I am distributing Mr. Crews memorandum to the other Senior Reactor Inspectors, so they might see the instructions.

John W. Flora
 John W. Flora
 Senior Reactor Inspector

Attachment:
 Memo, J. L. Crews to J. W. Flora,
 w/att, dated 11/3/69

- cc: J. L. Crews, CO:V
- N. C. Moseley, CO:I
- R. T. Carlson, CO:I
- F. J. Long, CO:II
- W. C. Seidle, CO:II
- H. D. Thornburg, CO:III
- G. Fiorelli, CO:III

IS/RAE 11/16/69
CR
YWR
JBH
LR
HO
MLC

9 7818

8003270 843