

bcc: Office of the Chairman (2)
 Commissioner Ramey
 Commissioner Tape
 Commissioner Johnson
 General Manager (2)
 General Counsel (2)
 Secretariat (2)

R. D. O'Neill, OCR (2)
 H. L. Price, REG
 M. M. Mann, REG
 C. A. Beck, REG
 R. L. Doan, REG
 P. A. Morris, DRL
 H. K. Shapar, GC
 REG Reading File
 E. G. Case, DRS
 L. D. Low, CO
 J. G. Davis, CO:II
 REG Central File

APR 15 1968

Mr. John T. Conway
 Executive Director
 Joint Committee on Atomic Energy
 Congress of the United States

Dear Mr. Conway:

This letter will inform you of two construction problems at the Florida Power and Light Company's reactor facilities, Turkey Point Units 3 and 4. These problems and their current status are as follows:

1. When the containment building pad forms for Unit No. 3 were removed, concrete voids up to one cubic foot in size were observed in the vicinity of approximately 25% of the 130 tendon trumpets which are imbedded in the concrete around the periphery of the pad. The tendon trumpets serve as anchors for the prestressed concrete containment building tendons.
2. A routine inspection of the installed Cadweld reinforcing bar splices by representatives of the Division of Compliance revealed quality control deficiencies in these splices. The deficiencies indicate inadequate quality control inspections by the applicant and his contractors.

The applicant, in conjunction with his consultants, is preparing a special report on these problems that will be submitted to the Commission for evaluation. Representatives of the Division of Compliance and their consultants from the Corps of Engineers and the University of Illinois are following on-site activities. They will review the methods and procedures that will be used to implement approved corrective actions.

We will inform you of any significant developments.

B305250087 680521
 PDR ADDCK 05000250
 A PDR

Sincerely yours,

(signed) Harold L. Price

(Please see previous yellow for DRL and GC concurrences.)

Harold L. Price
 Director of Regulation

OFFICE ▶	CO		DRL	OC	REG	DCR
SURNAME ▶	JPO'Reilly	RHEngelken	LDLow	see previous yellow	HLPrice	
DATE ▶	4/10/68	4/11			4/12/68	4/15/68