



Telegram

VEA509(2320)(1-03272303) PD 11/06/72 1923

ICS IPMVEIG MVN

ZCZC 00289 TDVE-MORRIS ILL 114 11-06 346P CST

PMS MR BOYCE CRIER DIRECTOR DIVN OF COMPLIANCE

US ATOMIC ENERGY COMMISSION

799 ROOSEVELT ROAD

GLEN ELLYN ILL 60137

SUBJECT: DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3

THIS WILL CONFIRM A CONVERSATION WITH MR H BLANCE OF

YOUR OFFICE AT 1430 HOURS THIS DATE CONCERNING HPCI SYSTEM

INOPERABILITY. AT 0240 NOVEMBER 6 1972, WHILE CONDUCTIN

POST MAINTENANCE SURVEILLANCE DURING UNIT START-UP, THE

HPCI STEAM VALVE 2-2501-4 IN THE DRY WELL WOULD NOT

OPEN. ALTHOUGH THE STARTUP AND HEAT-UP WERE HALTED AT THIS TIME, THE REACTOR PRESSURE DRIFTED UP TO ABOUT 100

LBS DURING INVESTIAGION OF THE VALVE PROBLEM. AT 0330, THE

SF-1201 (R5-69)

NOV 1972

SHIFT BEGAN A SHUT-DOWN OF THE UNIT. AT 0405, WITH REACTOR PRESSURE 77PSIG AND SUB-CRITICAL, VALVE TESTED SATISFACTORILY.

AT 0415 RESUMED START-UP. SATISFACTORILY TESTED HPCI

AT 0730 AT MINIMUM STEAM PRESSURE OF 110 PSI

W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON RURAL ROUTE 1 MORRIS ILLINOIS

1972 NOV 6 PM 10 41

TELEGRAMS (OTHER THAN MONEY ORDERS)

AGENCY DELIVERY requested? (YES-AGENT, NO-ADDRESSEE)

AGENT SECTION

ADDRESSEE SECTION

Nbr. & Name

Nbr.

Date did

Time did

To

To be mailed or station unit

By

Attempts to deliver (Indicate Date or BY)

By

Unit 2
HED
11/10/72

147

SF-1201 (R5-69)