



# Telegram

AC-1975 APR-7 OPR. NO. 17

TELEPHONE NBR. PH 3: 59858-266

TELEPHONED TO RG BY 15

DATE DLD. 4-8 TIME 9:25A

ATTEMPTS TO DELIVER: day 4/7 5:38P MC

VEB173(1549)(2-932208E097)PD 04/07/75 1549

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 64 04-07 0349P EST

PMS JAMES G KEPPLER REGIONAL DIRECTOR DIRECTORATE OF REGULATORY OPERATIONS, WUX 9999 ROOSEVELT Rd.

REGION 3 US NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT RD GLEN ELLYN IL 60137

SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION, UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1515 HOURS THIS DATE CONCERNING FAILURE OF DIESEL GENERATOR NUMBER 2 FAILED TO BUILD UP VOLTAGE FOLLOWING MONTHLY INSPECTION APRIL 5 1975. VS RELAY IS CAUSE OF FAILURE AND THIS WILL BE REPLACED 4-8-75.

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH EDISON CO RR #1 MORRIS ILLINOIS 60450

NNNN

APR 10 1975