



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
1600 E. LAMAR BLVD  
ARLINGTON TX 76011-4511

July 12, 2017

Mr. Jon O'Rullian  
Radiation Safety Officer  
Radiation Solutions, LLC  
343 E. 4<sup>th</sup> North, Suite 239  
Rexburg, ID 83440

SUBJECT: ACKNOWLEDGEMENT LETTER TO LICENSE NUMBER 11-35111-01

Dear Mr. O'Rullian:

We acknowledge receipt of your letter dated December 14, 2016, making your 1<sup>st</sup> notification for performing non-routine maintenance on shielded irradiators or gamma stereotactic radiosurgery units in accordance with License Condition 14. Please note that we conducted an inspection of licensed activities January 17-19, 2017. The results of this inspection can be found in NRC Inspection Report 030-38691/2016-001 and Notice of Violation (ML17066A196).

In addition, please note that you are required to notify this office 2 more times when performing non-routine maintenance on shielded irradiators or gamma stereotactic radiosurgery units in accordance with License Condition 14.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Thank you for your cooperation.

Sincerely,

*/RA/*

Jacqueline D. Cook, Senior Health Physicist  
Nuclear Materials Safety Branch B

Docket: 030-38691  
License: 11-35111-01  
Controls: 594615