

005140028

APRIL 25 1980

Docket Nos. 50-237
50-249
50-254
and 50-265

Mr. D. Louis Peoples
Director of Nuclear Licensing
Commonwealth Edison Company
P. O. Box 767
Chicago, Illinois 60690

Dear Mr. Peoples:

SUBJECT: EFFECT OF A DC POWER SUPPLY FAILURE ON ECCS PERFORMANCE

It has generally been recognized that the loss of a direct current (DC) power supply could disable several emergency core cooling system components and thereby could result in a limiting single failure condition for some breaks. The enclosed letter report was submitted to the NRC staff by the General Electric Company to provide a definitive, generic, reference analysis of the effects of DC power supply failures on ECCS conformance calculations. The NRC staff is reviewing the analysis which compares the peak cladding temperatures associated with various postulated DC power supply failure (ECCS equipment availability) cases to the peak cladding temperatures for a HPCI (small break) failure and LPCI injection valve (large break) failure cases. Since the study was based on plant design information which may have been incomplete or out-of-date, some uncertainty exists whether the worse ECCS system availability combinations have been identified for your operating BWRs. Accordingly, in order that we may have an adequate level of assurance that the systems combinations assumed in the generic analysis are conservative for Dresden Units 2 and 3 and Quad Cities Units 1 and 2, we request that you confirm the conclusion of the reference study regarding the minimum ECCS equipment availability with a DC power supply failure. Include in your response a list of the ECCS equipment that would be available for large and small (1) recirculation loop discharge breaks, and (2) recirculation loop suction breaks. The listing of equipment available should take into account not only DC power supply failure, but also loss of equipment due to water spillage.

Please provide a schedule for your response within 30 days of the receipt of this letter.

OFFICE					
SURNAME					
DATE					

This request for generic information was approved by GAO under clearance number B-160225(579010); this clearance expires October 31, 1980.

Sincerely,

Original Signed by
T. A. Ippolito
Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors

Enclosure:
General Electric Company letter
(R. E. Egel) to USNRC (P. S.
Check), "DC Power Source Failure
for BWR/3 and 4," dated November 1,
1978.

cc w/enclosure:
See next page

Distribution

- Docket
- ORB #3
- ORB #2
- Local PDR
- NRC PDR
- NRR Reading
- DEisenhut
- WGammill
- RVollmer
- JMiller
- LShao
- BGrimes
- Atty. OELD
- OI&E (3)
- TERA
- NSIC
- ACRS
- Tippolito
- SNorris
- RBevann
- DZiemann
- HSmith
- JShea

OFFICE ▶	ORB #3	ORB #3	ORB #3	ORB #2	ORB #2
SURNAME ▶	SNorris:mjf	RBevann:mjf	Tippolito	JShea	DZiemann
DATE ▶	4/ /80	4/ /80	4/ /80	4/ /80	4/ /80

Mr. D. Louis Peoples
Commonwealth Edison Company

- 3 -

cc:

Mr. D. R. Stichnoth
President
Iowa-Illinois Gas and
Electric Company
206 East Second Avenue
Davenport, Iowa 52801

Mr. John W. Rowe
Isham, Lincoln & Beale
Counselors at Law
One First National Plaza, 42nd Floor
Chicago, Illinois 60603

Mr. Nick Kalivianakas
Plant Superintendent
Quad Cities Nuclear Power Station
22710 - 206th Avenue - North
Cordova, Illinois 61242

U. S. Nuclear Regulatory Commission
Resident Inspector's Office
Dresden Station
RR #1
Morris, Illinois 60450

Moline Public Library
504 - 17th Street
Moline, Illinois 61265

Susan N. Sekuler
Assistant Attorney General
Environmental Control Division
188 W. Randolph Street
Suite 2315
Chicago, Illinois 60601

Mr. N. Chrissotimos, Inspector
US Nuclear Regulatory Commission
Box 756
Bettendorf, Iowa 52722

Mr. B. B. Stephenson
Plant Superintendent
Dresden Nuclear Power Station
Rural Route #1
Morris, Illinois 60450