

A0023

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-335 ST LUCIE 1
RECIPIENT: OREILLY, J.P.
ORIGINATOR: SCHMIDT, A.D.
COMPANY NAME: FL PWR & LIGHT
SUBJECT:

DOC DATE: 781013
ACCESSION NBR: 7810230166
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-039/03L-0 on 780930: during pwr oper, Digital Processing Sys malfunctioned due to momentary memory failure DDPS repaired & placed back in svc in 70 minutes.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
APC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
EMERGENCY PLAN BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
VOLLMER/BUNCH	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
K SEYFRIT/IE	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL


FOR ACTION
ORB#4 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR 44
ENCL 44

OCT 25 1978

NOTES:

A0 4
GD





October 13, 1978

PRN-LI-78-297

5

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-39
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: SEPTEMBER 30, 1978

TECHNICAL SPECIFICATION 3.1.3.3
DIGITAL DATA PROCESSING SYSTEM

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

ed woody
for
A. D. Schmidt
Vice President
Power Resources

REGULATORY DOCKET FILE COPY

WAK/cpc

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

REGULATORY DOCKET FILE COPY

781023 0166

A002
S/11