

USNRC REGION II
ATLANTA, GEORGIA



79 MAY 10 P 1: 18

May 2, 1979
L-79-110

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-335

Florida Power & Light Company has reviewed the subject Bulletin regarding the use of Velan swing check valves with incorrect weights. The Architect-Engineer and Nuclear Steam System Supplier are engaged in formalized programs to review valve purchase orders for St. Lucie Unit 1. The results to date are inconclusive, therefore, a status report will be issued by May 31, 1979.

Velan Engineering Corporation has also advised us that, as a parallel effort, they are reviewing their records to determine if they supplied us with any of the suspect valves.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU:MAS:cf

cc: Harold F. Reis, Esquire

7906120025

Ro 2
OFFICIAL COPY *BD*

