

USNRC REGION II
ATLANTA, GA



79 MAY 25 AIO: 50

May 22, 1979
L-79-130

Central File
50-335

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:EHW
50-335/79-09

Florida Power & Light Company has reviewed the subject Bulletin regarding General Electric Model AK-2 circuit breakers. We have determined that GE Model AK-2A circuit breakers are currently installed as part of the St. Lucie Unit 1 reactor trip switchgear.

A plant work order has been issued to perform the checks described in GE Service Advice Letter No. 175 (CPDD) 9.3 during the current (1979) refueling outage. These same checks will be incorporated into the periodic switchgear maintenance procedure prior to the next (1980) refueling outage.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/DKJ/cph

cc: Robert Lowenstein, Esquire

AD 2

7906260 293 Q
790193
OFFICIAL COPY 60

