



FLORIDA POWER & LIGHT COMPANY

July 19, 1979
L-79-197

JUL 24 10:19

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:WAR
50-335/79-15

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

Attachment

cc: Harold F. Reis, Esquire

7908240104

7910294
OFFICIAL COPY

ATTACHMENT

Re: RII:WAK
50-335/79-15

Finding

As required by Technical Specification 6.8.1, procedures shall be established and implemented.

Contrary to the above, procedures AP 0005720 and QI-2-PR/PSL2 were not implemented in that:

- AP 0005720, Revision 6, dated March 25, 1977, requires (Section 8.2.7) that personnel who make less than 80 percent on any portion of the annual examination shall attend lectures in those areas and 5 of 17 persons scoring less than 80 percent in one or more areas of the 1977 annual examination did not attend the lectures on those areas in 1978.
- QI-2-PR/PSL2, Revision 5, dated March 1977, requires (Section 4.3) that Department Heads establish departmental personnel training standards and, as of May 30, 1979, such standards had not been prepared for the Mechanical Maintenance, Electrical Maintenance, and Instrument and Control Departments.

Response

- A. The personnel who did not have a grade of 80% or better in the annual examination and who did not attend the required lectures were retested and received exam grades of 80 or greater.

In the future, failure to attend lectures as required will be noted as a deficiency against an individual's record, and make-up training will be required.

- B. Mechanical, Electrical, and I & C Maintenance Department personnel training standards comply with ANSI STD N18.1. Each of these departments have now documented this standard in their programs.



Finding

In the second paragraph on page 2 of a letter from Mr. P. Collins of the Operator Licensing Branch of the NRC to Mr. K. Harris of the St. Lucie Plant dated December 9, 1977, the licensee was instructed to assure that applications for the renewal of operator licenses contain statements indicating any area(s) where the applicant failed to participate in the accepted requalification program and indicate the actions taken or planned to compensate for such nonparticipation.

Contrary to the above, applications for the renewal of two licenses were submitted on February 23, 1979, for operators who had missed one or more required lectures, and no statement of the inadequacy nor of the corrective actions were included.

Response

Amended renewal applications for operator licenses were submitted detailing the deficiencies in the individual requalification program: attendance for the personnel involved.

The Training Supervisor is aware of this deviation and will assure that future applications for operator license renewal will include inadequacies and deficiencies of the operator as defined in Mr. Collins letter of 9/12/77.

