

DLK



January 8, 1980
L-80-5

Central File
50-389

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
St. Lucie Unit 2
Docket No. 50-389

Florida Power & Light Company has reviewed I. E. Bulletin 79-25 regarding the use of Westinghouse BFD/NBFD relays in safety-related systems. While the Nuclear Steam System Supplier indicates that these relays are not utilized in their supplied safety-related equipment, the Architect-Engineer is engaged in a review of safety-related equipment orders for St. Lucie Unit 2. The results are expected to be available by March 15, 1980.

If the Westinghouse BFD/NBFD relays are used in St. Lucie Unit 2, they will be either replaced or a program similar to that described in the bulletin will be initiated.

Very truly yours,

Robert E. Uhrig
Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JRP/ah

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operation Inspection
Washington, D. C. 20555

R

P

ORIGINAL COPY

