

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8002040478 DOC. DATE: 80/01/25 NOTARIZED: NO DOCKET #  
 FACID: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389  
 AUTH. NAME: AUTHOR AFFILIATION  
 UHRIG, R.E. Florida Power & Light Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards interim deficiency report re flange ratings. Final report will be submitted by 800501.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+6  
 TITLE: Construction Deficiency Report (10CFR50.55E)


NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	L	ENCL	ID CODE/NAME	L	ENCL
	14 PM BIRKEL	1	1	15 BC LWR #2	1	1
	20 CA LWR #2	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	22 DIR DPM	1	1
	23 OELO	1	1	AD/SITE TECH	1	1
	DIRECTOR DSE	1	1	GEOSCIENCES BR	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	S HANAUER	1	1	STRUCT ENG BR	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

FEB 7 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 47 ENCL 47


MA 1



[Faint, illegible text at the top of the page, possibly a header or introductory paragraph.]

[Faint header text]	[Faint header text]	[Faint header text]	[Faint header text]
1	[Faint text]	[Faint text]	[Faint text]
2	[Faint text]	[Faint text]	[Faint text]
3	[Faint text]	[Faint text]	[Faint text]
4	[Faint text]	[Faint text]	[Faint text]
5	[Faint text]	[Faint text]	[Faint text]
6	[Faint text]	[Faint text]	[Faint text]
7	[Faint text]	[Faint text]	[Faint text]
8	[Faint text]	[Faint text]	[Faint text]
9	[Faint text]	[Faint text]	[Faint text]
10	[Faint text]	[Faint text]	[Faint text]
11	[Faint text]	[Faint text]	[Faint text]
12	[Faint text]	[Faint text]	[Faint text]
13	[Faint text]	[Faint text]	[Faint text]
14	[Faint text]	[Faint text]	[Faint text]
15	[Faint text]	[Faint text]	[Faint text]
16	[Faint text]	[Faint text]	[Faint text]
17	[Faint text]	[Faint text]	[Faint text]
18	[Faint text]	[Faint text]	[Faint text]
19	[Faint text]	[Faint text]	[Faint text]
20	[Faint text]	[Faint text]	[Faint text]
21	[Faint text]	[Faint text]	[Faint text]
22	[Faint text]	[Faint text]	[Faint text]
23	[Faint text]	[Faint text]	[Faint text]
24	[Faint text]	[Faint text]	[Faint text]
25	[Faint text]	[Faint text]	[Faint text]
26	[Faint text]	[Faint text]	[Faint text]
27	[Faint text]	[Faint text]	[Faint text]
28	[Faint text]	[Faint text]	[Faint text]
29	[Faint text]	[Faint text]	[Faint text]
30	[Faint text]	[Faint text]	[Faint text]
31	[Faint text]	[Faint text]	[Faint text]
32	[Faint text]	[Faint text]	[Faint text]
33	[Faint text]	[Faint text]	[Faint text]
34	[Faint text]	[Faint text]	[Faint text]
35	[Faint text]	[Faint text]	[Faint text]
36	[Faint text]	[Faint text]	[Faint text]
37	[Faint text]	[Faint text]	[Faint text]
38	[Faint text]	[Faint text]	[Faint text]
39	[Faint text]	[Faint text]	[Faint text]
40	[Faint text]	[Faint text]	[Faint text]
41	[Faint text]	[Faint text]	[Faint text]
42	[Faint text]	[Faint text]	[Faint text]
43	[Faint text]	[Faint text]	[Faint text]
44	[Faint text]	[Faint text]	[Faint text]
45	[Faint text]	[Faint text]	[Faint text]
46	[Faint text]	[Faint text]	[Faint text]
47	[Faint text]	[Faint text]	[Faint text]
48	[Faint text]	[Faint text]	[Faint text]
49	[Faint text]	[Faint text]	[Faint text]
50	[Faint text]	[Faint text]	[Faint text]

[Faint text at the bottom left of the page, possibly a signature or date.]



January 25, 1980  
L-80-37

Mr. James P. O'Reilly, Director Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389  
FLANGE RATINGS

As previously reported to the Office of Inspection and Enforcement on December 21, 1979, we have determined that the flange material utilized for various safety related systems may not be consistent with the requirements of the ANSI B16.5-1968 code.

Pursuant to 10CFR50.55(e) requirements, an interim deficiency report is attached. A final deficiency report will be submitted by May 1, 1980.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/JP:ltm  
Attachment

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555  
(w/attachment)

*Bo 19  
5/11*

8002040

478  
PEOPLE...SERVING PEOPLE

