



March 25, 1980
L-80-103

MA/a

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-389
Damper Actuators

American Warming & Ventilating, Inc. has previously notified the NRC Office of Inspection and Enforcement (Washington, D. C. Office), per 10 CFR 21, of deficiencies in their damper actuators. Pursuant to 10 CFR 50.55(e) requirements, an interim deficiency report is attached, discussing the impact on St. Lucie Unit 2 damper actuators. A final deficiency report will be submitted by June 30, 1980.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JRP/ah
Attachment

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(w/attachment)

Harold F. Reis, Esquire