

USNRC REGION II
ATLANTA, GEORGIA



20 JUL 30 AM 11:46

July 24, 1980
L-80-236

Central File
50-389

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

10/2

Dear Mr. O'Reilly:

Re: RII:JPO
50-389
IE Bulletin 79-03A

It has been determined that neither ASME SA-312 nor A-312, Type 300 Series fusion welded stainless steel pipe is used or planned for use in St. Lucie Unit 2 safety-related systems. Therefore, the other items of this Bulletin are not applicable.

Very truly yours,

RE

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JRP/ah

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Harold F. Reis, Esquire

7

8008110 *108* ;

Q

OFFICIAL COPY

PEOPLE...SERVING PEOPLE

