

USNRC REGION II
ATLANTA, GEORGIA



30 AUG 12 AIO: 13

August 6, 1980
L-80-260

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-335
IE Bulletin 79-03A

Florida Power & Light Company has reviewed the subject Bulletin and has determined that the St. Lucie Unit 1 facility has no fusion welded ASME SA-312, type 304 stainless steel pipe in use or planned for use in safety-related systems.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/pa

cc: Harold F. Reis, Esquire

AO/E
2
OFFICIAL COPY 60

8009020.192