


USNRC REGION II
ATLANTA, GEORGIA



20 SEP 2 All : 34

August 29, 1980
L-80-285

Central File

AP/2

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO
50-389
I. E. Bulletin 80-19

Based on a review of our design, mercury-wetted relays are not used in the logic matrix of the reactor protective system (RPS) of St. Lucie Unit 2.

Yours very truly,

Robert E. Uhrig
Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/TCG/ah

cc: Director of Reactor Operations Inspections
Office of Inspections and Enforcement
Nuclear Regulatory Commission
Washington, D. C. 20555

Harold F. Reis, Esquire

8009 1110 693

OFFICIAL COPY

PEOPLE... SERVING PEOPLE

R