

0-049-034

HRC REGION II



RECEIVED DISTRIBUTION SERVICES UNIT

1980 DEC 9 PM 12 42

US HRC DISTRIBUTION SERVICES BRANCH

23 All: 13

September 18, 1980

PRN-LI-80-381

*Reviewed & Submitted
NEF 9/24/80
MST*

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-80-43
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: AUGUST 21, 1980

TECHNICAL SPECIFICATION 3.1.3.1e
CEDM #39 FAILURE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide thirty day notification of the subject occurrence.

Very truly yours,

A.D. Schmidt
A.D. Schmidt
Vice President
Power Resources

PLP/md

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

*4002
5/11*

OFFICIAL COPY

S 8012100404

SECRET

CONFIDENTIAL