


DISTRIBUTION
SERVICES UNIT

1981 JAN 2 PM 1 19

REGULATORY
SERVICES



January 16, 1981

PRN-LI-81-27

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-80-62
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: DECEMBER 18, 1980
TECHNICAL SPECIFICATION 4:6.1.3
MISSED SURVEILLANCE
PERSONNEL AIR LOCK LEAK TEST

The attached Licensee Event Report is being submitted in accordance with
Technical Specification 6.9 to provide 30 day notification of the subject
occurrence.

Very truly yours,

A.D. Schmidt
Vice President
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

A002
S
1/1

8102030462

5

