

USNRC REGION II
ATLANTA, GEORGIA



01 17 83:30

February 13, 1981
L-81-50

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Dear Mr. O'Reilly:

Re: R II: JPO
50-389
IE BULLETIN 80-21



Florida Power & Light Company has reviewed IE Bulletin 80-21 regarding the use of valve parts cast by Malcolm Foundry Company, Inc. On December 30, 1980, (L-80-424) FPL advised the NRC that a final response would be issued upon receipt of information from our safety related valve vendors. Although all of our major valve suppliers have responded to the bulletin by indicating valve parts cast by Malcolm Foundry are not used, two of our equipment vendors have not provided a response yet. Therefore we anticipate closing out this bulletin by May 29, 1981.

Very truly yours,

Robert E. Uhrig
Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/TCG/mc

cc: U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Construction Inspection

X02

Harold F. Reis, Esquire

