


March 27, 1981

L-81-134

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

Re: RII:JPO
50-335
IE Bulletin 81-01

Florida Power & Light Company has reviewed the subject Bulletin. St. Lucie Unit 1 does not have INC mechanical snubbers in any safety related systems. The visual and manual testing of the mechanical snubbers used on the safety-related systems will be performed during our next refueling outage. The next refueling is currently scheduled for October, 1981.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JEM/mbd

cc: Harold Reis, Esquire

Director, Nuclear Regulatory Commission Office
of Inspection and Enforcement
Washington, D. C. 20555

8104090 616
Q

