

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8306200194 DOC. DATE: 83/06/16 NOTARIZED: NO
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.
 AUTH. NAME: UHRIG, R.E. AUTHOR AFFILIATION: Florida Power & Light Co.
 RECIP. NAME: EISENHUT, D.G. RECIPIENT AFFILIATION: Division of Licensing

DOCKET #
05000389


SUBJECT: Forwards corrected Tech Spec Table 3.3-10 re accident monitoring instrumentation submitted in 830615 application to amend license. Superscript on min channels operable should have two astericks instead of three.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	A/D LICENSNG		1	0		LIC BR #3 BC		1	0
	LIC BR #3 LA		1	0		NERSES, V. 01		1	1
INTERNAL:	ELD/HDS2		1	0		IE FILE		1	1
	IE/DEPER/EPB 36		3	3		IE/DEPER/IRB 35		1	1
	IE/DEQA/QAB 21		1	1		NRR/DE/AEAB		1	0
	NRR/DE/CEB 11		1	1		NRR/DE/EHEB		1	1
	NRR/DE/EQB 13		2	2		NRR/DE/GB 28		2	2
	NRR/DE/MEB 18		1	1		NRR/DE/MTEB 17		1	1
	NRR/DE/SAB 24		1	1		NRR/DE/SGEB 25		1	1
	NRR/DE/SGEB 30		1	1		NRR/DHFS/HFEB40		1	1
	NRR/DHFS/LGB 32		1	1		NRR/DHFS/PSRB		1	1
	NRR/DL/SSPB		1	0		NRR/DSI/AEB 26		1	1
	NRR/DSI/ASB		1	1		NRR/DSI/CPB 10		1	1
	NRR/DSI/CSB 09		1	1		NRR/DSI/ICSB 16		1	1
	NRR/DSI/METB 12		1	1		NRR/DSI/PSB 19		1	1
	NRR/DSI/RAB 22		1	1		NRR/DSI/RSB 23		1	1
	REG FILE 04		1	1		RGN2		3	3
	RM/DDAMI/MIB		1	0					
EXTERNAL:	ACRS 41		6	6		BNL (AMDTs ONLY)		1	1
	DMB/DSS (AMDTs)		1	1		FEMA-REP DIV 39		1	1
	LPDR 03		1	1		NRC PDR 02		1	1
	NSIC 05		1	1		NTIS		1	1

TOTAL NUMBER OF COPIES REQUIRED: LTR 54 ENCL 47



June 16, 1983
L-83-363

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: St. Lucie Unit 2
Docket No. 50-389
Clarification of Proposed License Amendment
PORV Indication L-83-362 June 15, 1983

In our June 16, 1983 telecom with your Mr. V. Nerses and staff reviewer R. Stevens, we discussed the action statement for Instrument line 12 under Minimum Channels Operable that was in our June 15, 1983 amendment request. Following our telephone conversation we have determined that the superscript on the Minimum Channels Operable should be two asterisks not three. A copy of the corrected TABLE 3.3.-10 is attached.

Very truly yours,

J. A. De Mastry
Robert E. Uhlig
Vice President
Advanced Systems and Technology

REU/JNB/cab

Attachment

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

Uray Clark, Administrator
Radiological Health Services
Department of Health & Rehabilitative Services
1323 Winewood Boulevard
Tallahassee, Florida 32301

8306200194 830616
PDR ADOCK 05000389
PDR

Boo!
11