



December 19, 1984  
L-84-383

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Reportable Event 84-13  
St. Lucie Unit 2  
Date of Event: November 19, 1984  
Spurious Reactor Trip

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

J. W. Williams, Jr.  
Group Vice President  
Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC  
Harold F. Reis, Esquire  
PNS-LI-84-461-1

~~8501030195~~

IE 22  
111

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>St. Lucie Unit 2</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 3 8 9</b>	PAGE (3) <b>1 OF 0 1</b>
--	---	-----------------------------

TITLE (4)  
**Spurious High Startup Rate Trip**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
7	7	84	84	013	00	12	19	84	N/A		
									DOCKET NUMBER(S) <b>0 5 0 0 0</b>		

OPERATING MODE (9) <b>2</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) <b>0 0 0</b>	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.38(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)							
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)							

LICENSEE CONTACT FOR THIS LER (12)

NAME <b>Dan West, Shift Technical Advisor</b>	TELEPHONE NUMBER
	AREA CODE: <b>3 10 15</b> NUMBER: <b>4 16 15 1 13 15 15 10</b>

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X									

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a normal reactor startup, wide range nuclear instrumentation circuitry noise resulted in a spurious high startup rate trip.  
Cause of the noise could not be determined.  
There was no adverse effect on the health or safety of the public.

8501030195 841219  
PDR ADOCK 05000389  
S PDR

IE 22  
||

