

Docket Nos. 50-237  
and 50-249

SEP 3 1969

DISTRIBUTION:  
Docket Files (2)  
DRL Reading  
RPB-2 Reading  
R. S. Boyd  
R. L. Tedesco  
H. Denton  
H. Steele (2)

Dr. Stephen H. Hanauer  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Hanauer:

Eighteen copies of the following are transmitted  
for the review of the Committee:

COMMONWEALTH EDISON COMPANY  
(Dresden NPS Units 2 and 3)

Commonwealth Edison letter dated September 12, 1969,  
transmitting as Amendment No. 19 for Dresden 2 and  
Amendment No. 20 for Dresden 3, the following:

1. Additional information on the significance of failure of the Rod Block Monitor System.
2. Revised proposed technical specifications.
3. Additional information on the seismic design of the plant.

Sincerely,

*Peter A. Morris*

Peter A. Morris, Director  
Division of Reactor Licensing

Enclosures:  
As stated

OFFICE ▶	DRL:RP	DRL:RP			
SURNAME ▶	HSteele:hs	RLTedesco			
DATE ▶	9/2/69	9/3/69			