

October 25, 1972

Docket No. 50-249

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:


Sixteen (16) copies of the following are transmitted for the Committee's information:

Letter from Commonwealth Edison Company dated October 13, 1972, reporting that the set points of two of the reactor low pressure permissive switches drifted beyond the values established in the Dresden Unit 3 Technical Specifications.

Distribution

Docket File
BraeCh Reading

Sincerely,



Donald J. Skovholt
Assistant Director
for Operating Reactors
Directorate of Licensing

Enclosures:
As stated

b6
b7c

OFFICE ►	L:ORB #2						
SURNAME ►	RMDiggs:sjh						
DATE ►	10/25/72						