

50-249

January 15, 1973

Docket No. (See attached list)

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545


Dear Dr. Siess:

Sixteen (16) copies of the following are transmitted for the
Committee's information:

Form letter to applicants on attached list dated December 22, 1972,
regarding a deficiency in the control circuit design that warrants
a review of the control circuits of all facilities to assure that
these types of deficiencies do not exist or are corrected if they
do exist.

Distribution
Docket File
Branch Reading File

Sincerely,


Donald J. Skovholt
Assistant Director for
Operating Reactors
Directorate of Licensing

Enclosures:
As stated

kw

OFFICE ▶	L:OR-1					
SURNAME ▶	<i>SA Teets:dc</i>					
DATE ▶	1/15/73					

Docket Nos. 50-220, 50-263, 50-133, 50-245, 50-155, 50-409,
50-10, 50-237, 50-249, 50-254, 50-265, 50-29, 50-3, 50-206,
50-213, 50-244, 50-261, 50-171