

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9106280190 DOC. DATE: 91/06/24 NOTARIZED: NO DOCKET #
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 SAGER, D.A. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Unusual or Important Environ Event" to correct
 typo detected in paragraph A of attachment in util ltr
 L-91-158.

DISTRIBUTION CODE: IE23D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Environmental Event Report (per Tech Specs)

NOTES:


	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 LA		3	3		PD2-2 PD		1	1
	NORRIS, J		1	1					
INTERNAL:	ACRS		5	5		NRR/DREP/PEPB9D		1	1
	NRR/PMAS/ILRB12		1	1		OGC/HDS3		1	1
	REG FILE 01		1	1		RGN2		1	1
	RGN2/DRSS/EPRPB		1	1					
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 18 ENCL 18

R
I
D
S
/
A
D
D
S
/
A
D
D
S





JUN 24 1991
L-91-179
10 CFR 50.36(b)

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: St. Lucie Unit 2
Docket No. 50-389
Environmental Protection Plan Report
Date of Event: May 13, 1991
Unusual or Important Environmental Event

The attached Report is being submitted to correct a typographical error detected in paragraph (A) of the attachment in Florida Power & Light letter# L-91-158.

If there are any questions please contact us.

Very truly yours,

DA Sager
D. A. Sager
Vice President
St. Lucie Plant

DAS/JJB/kw

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #457

9106280190 910624
PDR ADOCK 05000389
P PDR

an FPL Group company

IE23
11



14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200

DESCRIPTION OF A FISHKILL EVENT

AT THE ST. LUCIE POWER PLANT

The following are sequential responses for information required by the Plant's Environmental Protection Plans:

- A. Crevelle jack in the St. Lucie Power Plant intake canal are dying. Mortality was first observed May 3, 1991. On May 13, 1991, it was determined that the FPL criteria for a fishkill had been met. By May 21, 1991, approximately 100 dead fish had been found on intake canal berms and on barrier nets in the canal. By May 30, 1991, approximately 1,000 dead fish had been recovered. Crevelle jacks are the only species affected. Plant operations have been normal with no unusual or causative conditions noted.
- B. Probable cause of mortality is insufficient food supply. Based on an examination of dead fish the following support a starvation hypothesis: empty stomachs, thinness of the fish and gonad size reduction. The jacks have eaten all the bait fish in the canal and will strike any bright object in the canal.
- C. Corrective action has been to remove the dead fish and dispose of them on site. Observations on the fauna in the canal are on-going to help understand this event.
- D. Corrective action is underway and involves rebuilding the velocity caps. When the repair is complete, entrapment of jacks may be reduced.
- E. The Nuclear Regulatory Commission, via Jan Norris, St. Lucie Plant Project Manager, was notified of the event on May 15, 1991. FPL's determination of reportability was made by FPL biological specialists in the Company's Environmental Affairs Department through a systematic evaluation of the event.

