

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9112060384 DOC. DATE: 91/11/25 NOTARIZED: NO DOCKET # 05000335
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.
 AUTH. NAME: SAGER, D.A. AUTHOR AFFILIATION: Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC request for review of AEOD rept, "Experience w/Pump Seals Installed in Reactor Coolant Pumps Mfg by Bryon Jackson."

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD2-2 LA		1	1		PD2-2 PD		1	1	
	NORRIS, J		2	2						
INTERNAL:	ACRS		6	6		NRR/DET/ECMB 7D		1	1	
	NRR/DET/ESGB		1	1		NRR/DOEA/OTSB11		1	1	
	NRR/DST 8E2		1	1		NRR/DST/SELB 7E		1	1	
	NRR/DST/SICB8H7		1	1		NRR/DST/SRXB 8E		1	1	
	NUDOCS-ABSTRACT		1	1		OG/LFMB		1	1	
	OGC/HDS3		1	0		<u>REG FILE</u> 01		1	1	
	RES/DSIR/EIB		1	1						
EXTERNAL:	NRC PDR		1	1		NSIC		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL ~~22~~ ⁰

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



November 25, 1991

L-91-319
10 CFR 50.4

Thomas M. Novak, Director
Division of Safety Programs
U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Dear Mr. Novak:

RE: St. Lucie Unit 1
Docket No. 50-335
Response to NRC Request for Review

NRC letter (T. M. Novak to D. A. Sager) dated September 27, 1991 provided St. Lucie a copy of the draft AEOD report "Experience with Pump Seals Installed in Reactor Coolant Pumps Manufactured by Byron Jackson." Your letter requested St. Lucie to review the report and provide comments on the technical accuracy of the data relied on in the report.

The forced outage for St. Lucie Unit 1 referenced in Table 5 page 28 did not occur on February 16, 1990 as indicated in your report. St. Lucie Unit 1 did have a forced outage to replace a leaking seal on July 2, 1990. This forced outage was reported in the Monthly Operating Report for St. Lucie Unit 1 submitted by FPL letter L-90-304 dated August 20, 1990.

Please contact us if there are any questions about this submittal.

Very truly yours,

D. A. Sager
Vice President
St. Lucie Plant

DAS/GRM/kw

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #569-91

9112060384 911125
PDR ADOCK 05000335
PDR

Adool
1/10



Handwritten marks and scribbles in the top right corner.

Handwritten marks and scribbles in the bottom left corner.

Handwritten marks and scribbles in the bottom right corner.