



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**

REGION III  
2443 WARRENVILLE RD. SUITE 210  
LISLE, IL 60532-4352

August 16, 2017

Mr. Bryan C. Hanson  
Senior VP, Exelon Generation Company, LLC  
President and CNO, Exelon Nuclear  
4300 Winfield Road  
Warrenville, IL 60555

**SUBJECT: BRAIDWOOD STATION, UNITS 1 AND 2 – NOTIFICATION OF  
AN NRC BIENNIAL LICENSED OPERATOR REQUALIFICATION  
PROGRAM INSPECTION AND REQUEST FOR INFORMATION**

Dear Mr. Hanson:

In a telephone conversation on May 30, 2017, between Mr. Michael Bielby, Senior Operations Engineer, the U.S. Nuclear Regulatory Commission (NRC) lead inspector for this inspection, and Mr. John Taff, Licensed Operator Requalification Training Lead, final arrangements were made for the NRC to inspect the licensed operator requalification program at the Braidwood Station, Units 1 and 2. The inspection is planned for the week of September 25, 2017, which coincides with your regularly scheduled requalification examination cycle. The staff at your facility should prepare and conduct the requalification examinations in accordance with your NRC-approved requalification program.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 55.59(c), the NRC may request facility licensees to submit their biennial comprehensive requalification written examinations and annual operating tests as necessary to support the NRC's inspection program needs. In order to minimize the impact that the inspection has on the site and to ensure a productive inspection, we have enclosed a request for documents needed for the inspection. Please furnish the items listed in the first group of the attached enclosure, needed to support our in-office inspection activities, to the NRC by September 15, 2017. Please have the items listed in the second group of the attached enclosure available for the inspectors during the onsite portion of the inspection activities. Mr. Taff has been advised of this request.

Thank you for your cooperation in this matter. If there are any questions regarding either the inspection, or the material requested in the enclosure, please contact me at 630-829-9762 or via e-mail at [Michael.Bielby@NRC.gov](mailto:Michael.Bielby@NRC.gov).

This letter does not contain new or amended information collection requirements subject to the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 et seq.). Existing information collection requirements were approved by the Office of Management and Budget, Control Number 3150-0011. The NRC may not conduct or sponsor, and a person is not required to respond to, a request for information or an information collection requirement unless the requesting document displays a currently valid Office of Management and Budget Control Number.

This letter and its enclosure will be available for public inspection and copying at <http://www.nrc.gov/reading-rm/adams.html> and at the NRC Public Document Room in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding."

Sincerely,

***/RA Randal Baker Acting for/***

Michael E. Bielby, Sr., Senior Operations Engineer  
Operations Branch  
Division of Reactor Safety

Docket Nos. 50-456; 50-457  
License Nos. NPF-72; NPF-77

Enclosure:  
Requested Information to Support Licensed  
Operator Requalification Program and  
Licensed Operator Performance Inspection  
(IP 71111.11)

cc: Distribution via LISTSERV®

Letter to Bryan Hanson from Michael Bielby, Sr. dated August 16, 2017

SUBJECT: BRAIDWOOD STATION, UNITS 1 AND 2 – NOTIFICATION OF AN NRC BIENNIAL LICENSED OPERATOR REQUALIFICATION PROGRAM INSPECTION AND REQUEST FOR INFORMATION

DISTRIBUTION:

Jeremy Bowen  
RidsNrrDorLpl3  
RidsNrrPMBraidwood Resource  
RidsNrrDirslrib Resource  
Cynthia Pederson  
James Trapp  
Richard Skokowski  
Allan Barker  
Carole Ariano  
Linda Linn  
DRPIII  
DRSIII  
Nancy Salgado, NRR  
Colleen Schmidt, DRS

ADAMS Accession Number: ML17228A797

OFFICE	RIII	RIII	RIII	RIII
NAME	RBaker for MBielby:jw			
DATE	08/16/17			

**OFFICIAL RECORD COPY**

**REQUESTED INFORMATION TO SUPPORT LICENSED OPERATOR REQUALIFICATION PROGRAM AND LICENSED OPERATOR PERFORMANCE INSPECTION (IP 71111.11)**

Please provide the following information on a CD/DVD, if possible, by September 15, 2017.

1. One complete version of a biennial requalification written examination administered during the training cycle.
2. Ten (10) job performance measures (JPMs) and four (4) simulator scenarios associated with an annual requalification operating test required by Title 10 of the *Code of Federal Regulations* 55.59(a)(2). The JPMs and scenarios to be reviewed should include those that will be observed during the onsite portion of this inspection, with any remaining JPMs and scenarios reviewed selected from other weeks within the same training cycle.
3. Complete versions of the reference materials used to develop and administer the written examination and operating test. (Refer to NUREG-1021, ES-201 Attachment 3, Reference Material Guidelines for Initial Licensing Examinations.)
4. Spreadsheets and/or test outlines which show the usage of written examination questions, JPMs, and simulator scenarios.
5. A list (or lists) of licensee-identified issues associated with licensed operator errors or other licensed operator performance problems which have occurred in the actual plant/main control room since the last biennial requalification program, their associated corrective actions, and if these issues were incorporated into requalification training. (These issues are likely documented in condition/problem identification reports, licensee-conducted audits and assessments, and in industry operating experience reports, etc.)
6. Facility licensee procedures for licensed operator requalification training and examination, including examination security procedures.
7. A schedule of the licensee's examination activities during the on-site inspection week.

Please have the following information available for U.S. Nuclear Regulatory Commission (NRC) review on September 25, 2017.

1. Licensed operator pass/fail statistics for any NRC-required requalification examination that has been completed (see Table 03.02-1, Examination Results).
2. An overall schedule of the facility licensee's requalification program since the last biennial inspection (cycle weeks, training topics, etc.).
3. A list and descriptions of any examination security problems since the last biennial inspection (likely documented in training department condition/problem identification reports).
4. Records for licensed operator requalification training attendance, licensed operator performance in requalification, licensed operator remedial training, individual licensed operator medical records, and records for maintaining an active license and license re-activation.
5. Simulator testing, maintenance, modification, and performance records. Simulator corrective action records, including lists of open/closed simulator deficiencies, and corrective actions taken.

Enclosure