

**HDP-PR-FSS-701, Final Status Survey Plan Development  
APPENDIX P-6  
FSS FIELD LOG**

**Survey Area:** LSA 04                      **Description:** \_\_\_\_\_

**Survey Unit:** 05                              **Description:** \_\_\_\_\_

**Comments:**

**FSS Field Log:**

<b><u>Date/Time:</u></b>	<b><u>Observation or Comment:</u></b>	<b><u>Technician</u></b>
5/4/16 – 6:00	Perform pre-operational check of Ludlum Instruments 2221 G and N.	JW, JM, DL
5/4/16 – 9:30	Begin Final Status GWS. The surface is dry and clear. 3 HP's will perform all activities in this LSA. This LSA is a class 3 and we will ensure 10% coverage. The weather is partly cloudy, mid 60's.	JW, JM, DL JW, JM, DL JW, JM, DL
5/4/16 – 11:30	Break for lunch.	JW, JM, DL
5/4/16 – 13:00	Begin sampling.	JW, JM, DL
5/4/16 – 16:00	6 locations completed. L04-05-(01-08) and L04-05-(12-19). The L04-05-(9-11) and L04-05-(20-22) will be sampled tomorrow.	JW, JM, DL
5/4/16 – 16:30	Post operational check on Ludlum Instruments. All samples locked in sample cage. All sample equipment cleaned and put away.	JW, JM, DL JW, JM, DL
5/5/16 – 8:30	Gather tools and sampling equipment for the remaining samples. The weather is cool, breezy with temps in the low 60's. The soil is dry.	JW, JM, DL
5/5/16 – 9:00	Begin sampling L04-05-(9-11) and L04-05-(20-22).	JW, JM, DL
5/5/16 – 10:30	Complete sampling.	JW, JM, DL
5/5/16 – 11:00	Samples prepared for shipment, in sample cage, in 2 coolers.	JW, JM, DL
5/5/16 – 11:30	Sampling equipment put away.	JW, JM, DL JW, JM, DL
5/24/16 – 12:30	Assemble sampling equipment. We are going to be taking systematic samples in this LSA because we had some elevated biased samples which will change this unit from a class 3 to a class 2. We will perform more GWS at a later date. The weather today is warm and sunny.	JW, JM, DL
5/24/16 – 13:00	Begin sampling.	JW, JM, DL
5/24/16 – 15:00	Complete sampling for today. L04-05-(37-48) have been taken.	JW, JM, DL
5/24/16 – 15:30	Samples placed in cooler in sample cage.	JW, JM, DL
5/24/16 – 16:00	Sampling equipment put away.	JW, JM, DL JW, JM, DL
5/25/16 – 09:00	Assemble sampling equipment. We are going to take the remaining systematic samples today. The weather today is warm and partly cloudy. The surface is dry with some weeds in certain areas.	JW, JM, DL
5/25/16 – 09:45	Begin sampling.	JW, JM, DL

HDP-PR-FSS-701, Final Status Survey Plan Development  
APPENDIX P-6  
FSS FIELD LOG

Survey Area: LSA 04 Description: \_\_\_\_\_

Survey Unit: 05 Description: \_\_\_\_\_

Comments:

<u>Date/Time:</u>	<u>Observation or Comment:</u>	<u>Technician</u>
<u>5/25/16 – 11:30</u>	<u>Break for lunch.</u>	<u>JW, JM, DL</u>
<u>5/25/16 – 12:30</u>	<u>Resume sampling activities.</u>	<u>JW, JM, DL</u>
<u>5/25/16 – 13:30</u>	<u>Complete all sampling. L04-05-(25-36) all taken. All samples taken to sample cage, placed in coolers, and prepared for shipment.</u>	<u>JW, JM, DL</u>
<u>5/25/16 – 14:00</u>	<u>All sampling equipment put away.</u>	<u>JW, JM, DL</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____