

WESTERN UNION INCOM

Bellog

USAEC HQS GTWN

TLXA081 (49)DEA083

Regulatory

File Cy. 50-237
50-249

DE JLA105 NL RC PDB MORRIS ILL 7

1971 AUG 8 - AM 8 10

DR. PETER A MORRIS DIRECTOR DIVN OF REACTOR LICENSING USAEC

WASHDC 20545



U.S. ATOMIC ENERGY COMM.
TWX UNIT

DPR19 AND 25 DRESDEN NUCLEAR POWER STATION UNITS 2 AND 3

THIS WILL CONFIRM CONVERSATION 1430 THIS DATE WITH E A JORDON REGARDING AN UNPLANNED LIQUID RELEASE OCCURING FROM 0945 TO 1105 THIS DATE REPORTABLE UNDER SECTION 66A3 THIS UNPLANNED RELEASE OCCURED AS A RESULT OF AN ERROR IN VALVE LINE UP CAUSING B FLOOR DRAIN SAMPLE TANK RELEASE AT A RATE ESTABLISHED FOR THE A FLOOR DRAIN SAMPLE TANK PRIOR TO ESTABLISHING THE PROPER DISCHARGE RATE OF THE B TANK. THE RESULTING ACTIVITY IN THE DISCHARGE WATER WAS 30 PICOCURIES PER LITER OR 30 PERCENT OF THE ALLOWABLE. A REVIEW OF FACTORS WHICH CONTRIBUTED TO THE ERROR IS BEING REVIEWED AND ACTION IS BEING TAKEN TO PREVENT RECURRENCE

H K HOYT SUPT DRESDEN NUCLEAR POWER STATION

DPR19 25 2 3 1430 0945 1105 66JA3.?



420PP

USAEC HQS GTWN

3559

B