



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690


May 17, 1976

Regulatory Docket File



Mr. Dennis L. Ziemann, Chief
 Operating Reactors - Branch 2
 Division of Operating Reactors
 U.S. Nuclear Regulatory Commission
 Washington, D.C. 20555

Subject: Dresden Station Unit 3
 Quad-Cities Station Units 1 and 2
 Feedwater Nozzle Blend Radius
 Cracking Repair Report
 NRC Dkts. 50-249, 50-254, and 50-265



Dear Mr. Ziemann:

Enclosed are reports of the feedwater nozzle cladding crack repair for Dresden Unit 3, Quad-Cities Unit 1 and Quad-Cities Unit 2 as requested by your staff during the May 6, 1976 meeting with representatives of the Commonwealth Edison Company.

Very truly yours,

Michael A. Abrell

G. A. Abrell
 Nuclear Licensing Administrator
 Boiling Water Reactors

- Enclosure (1): Dresden Unit 3 Feedwater Nozzle Blend Radius Cracking Repair Report
- Enclosure (2): Quad-Cities Unit 1 Feedwater Nozzle Cladding Crack Repair Report
- Enclosure (3): Quad-Cities Unit 2 Feedwater Nozzle Clad Crack Report Report