



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

Regulatory

File Cy.

March 21, 1974



Mr. J. F. O'Leary, Director
 Directorate of Licensing
 Office of Regulation
 U.S. Atomic Energy Commission
 Washington, D.C. 20545


**Subject: Dresden Station Units 2 and 3 - Secondary
 Containment Leak Rate Test Summary, AEC
 Dkts 50-237 and 50-249**

Dear Mr. O'Leary:

Attached in accordance with Section 6.6.E of Appendix A to DPR-19 and DPR-25 is a summary technical report of the secondary leak rate tests performed for the Dresden Units 2 and 3 reactor buildings on February 28, 1974. This test was performed in accordance with Section 4.7.C.1.c of the Dresden Units 2 and 3 Technical Specifications.


One signed original and 39 copies of this report are submitted for your use.

Very truly yours,


 J. S. Abel

Nuclear Licensing Administrator
 Boiling Water Reactors

Att.



2706