

James G. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Telecopied Date 2-28-75
or
Telegrammed: CE 4:10
DC 3:50
By am

cc:
J. F. O'Leary, Director
Directorate of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUBJECT: DPN-25, Dresden Nuclear Power Station, Unit 3.

This will confirm a conversation with Mr. P. JOHNSON of your office at 1540 hrs this date concerning FAILURE OF AN OUTBOARD MAIN STEAM ISOLATION VALVE, AO 3-203-2A, TO ACTUATE THE REACTOR PROTECTION SYSTEM LOGIC DURING SURVEILLANCE TO CHECK THE "NOT FULL OPEN" SIGNAL. THE FAILURE APPEARS TO BE DUE TO A FAULTY LIMIT SWITCH ON THE VALVE. THE SUBJECT RPS SYSTEM RELAY WAS DE-ENERGIZED UNTIL REPAIRS COULD BE MADE.

To Call:
CE - 5-858-2660x16 (auto) - on 6
DC - 9-1-381-492-7617 (auto)
WU - 815-942-6449/4321

Station Dist: Originator (copy)

B. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R.R. #1
Morris, IL 60450