REGULATORY 1 ORMATION DISTRIBUTION SYS (RIDS)

ACCESSION NBR:8208300249 DOC.DATE: 82/08/20 NOTARIZED: NO DOCKET # FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244

AUTH.NAME AUTHOR AFFILIATION

MAIER, J.E. Rochester Gas & Electric Corp.

RECIPIENT AFFILIATION

CRUTCHFIELD, D. Operating Reactors Branch 5

SUBJECT: Notifies that response to 820617 request for status info re unresolved safety issues will be provided by late Sept 1982 for inclusion in safety evaluation. No short-term safety implication associated w/respose delay.

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR __ ENCL __ SIZE:______
TITLE: OR Submittal: General Distribution

NOTES: NRR/DL/SEP 1cy.

05000244

	RECIPIENT ID CODE/NAME ORB #5 BC 01		COPIES LTTR ENCL 7 7		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
INTERNAL:	INTERNAL: ELD/HDS4 NRR/DL DIR NRR/DSI/RAB RGN1		1 1 1	0 1 1 1	NRR/DHFS NBR/BL/OR REG FILE		1 1 1	1 0 1
EXTERNAL:	ACRS NRC PDR NTIS	09 02	10 1	1 0 1 1	LPDR NSIC	03 05	1	1
NOTES:			1	1				

ه المستوية الم المستوية ال

M





ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER Vice President

TELEPHONE AREA CODE 716 546-2700

August 20, 1982

Director of Nuclear Reactor Regulation Mr. Dennis M. Crutchfield, Chief Operating Reactors Branch No. 5 U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Unresolved Safety Issues

R. E. Ginna Nuclear Power Plant

Docket No. 50-244

Dear Mr. Crutchfield:

In your letter dated June 17, 1982, RG&E was requested to furnish status information relative to Unresolved Safety Issues. This information was requested within 60 days, in order to enable the staff to expeditiously review and evaluate the status of these items at Ginna for inclusion in the Full Term Operation License conversion SER.

Based on the present schedule for this SER of mid-October 1982, RG&E is planning to provide the requested information by late September 1982. This should provide the necessary time for incorporation into the SER. Since the subject of this letter addresses the status of industry-generic Unresolved Safety Issues, rather than any plant-specific concerns, there are no short-term safety implications associated with this response delay.

Very truly yours,

8208300249 820820 PDR ADOCK 05000244 ,ř.,**,** $\Phi_{ij} = \Phi_{ij}$