REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

DOC.DATE: 90/01/26 NOTARIZED: NO DOCKET # ACCESSION NBR:9002120255 FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244 AUTHOR AFFILIATION AUTH.NAME Rochester Gas & Electric Corp. MECREDY, R.C. RECIPIENT AFFILIATION RECIP. NAME Document Control Branch (Document Control Desk) R SUBJECT: Forwards Rev 1 to LER 89-016 to correct event date on page 1. DISTRIBUTION CODE: IE28T COPIES RECEIVED:LTR _ \ ENCL SIZE: TITLE: Licensee Event Report (LER) & Part 21 Rept Combination (50 Dkt S 05000244 NOTES: License Exp date in accordance with 10CFR2,2.109(9/19/72). COPIES RECIPIENT COPIES RECIPIENT ID CODE/NAME LTTR ENCL LTTR ENCL ID CODE/NAME PD1-3 LA 1 1 PD1-3 PD JOHNSON, A L 2 ACRS MOELLER INTERNAL: ACRS MICHELSON 1 AEOD/DOA ACRS WYLIE S AEOD/ROAB/DSP AEOD/DSP/TPAB IRM TECH ADV DEDRO NRR/ADP/DRP14E4 IRM/DCTS/DAB 1 1 NRR/DET/ECMB 9H NRR/ADSP DIR 1 NRR/DET/ESGB 8D NRR/DET/EMEB9H3 1 1 NRR/DLPQ/LPEB10 NRR/DLPQ/LHFB11 1 1 NRR/DOEA/OEAB11 NRR/DOEA/OGCB11 1 NRR/DREP/PRPB11 NRR/DRIS/RVIB9D 1 NRR/DREP/PRAB10 NRR/DRIS/RSIB9A ī NRR/DST 8E2 NRR/DST/SICB 7E NRR/DST/SRXB 8E NRR/DST/SELB 8D 0 NRR/DST/SPLB8D1 1 1 1 1 NSIC SILVER, E REG FILE 02 1 1 REGION 1 R REGION 3 1 1 REGION-2 REGION 5 REGION 4 1 RES/DSIR/EIB RES MORISSEAU, D FILE 01 RES/DSR/PRAB RGN1 D 4 4 1 1 1 1 1 1 INPO RECORD CTR EXTERNAL: EG&G WILLIAMS, S S L ST LOBBY WARD LPDR NSIC MAYS,G NRC PDR NSIC MURPHY, G.A NUDOCS FULL TXT D D NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED 55 ENCL 54 TOTAL NUMBER OF COPIES REQUIRED: LTTR

S





FIGURE 15 AND ELECTRIC CORPORATION • 89. EAST AVENUE, ROCHESTER, N.Y. 14649-0001

January 26, 1990

TELEPHONE AREA CODE 716 546:2700

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Subject:

LER 89-016 (Revision 01), Due To a Design Deficiency The Failure of the SI Block/Unblock Switch Could Render Some Automatic Actuation Features of Both

Trains of SI Inoperable

R.E. Ginna Nuclear Power Plant

Docket No. 50-244

In accordance with 10 CFR 50.73, Licensee Event Report System, item (a)(2)(v)(D) and (a)(2)(vi), which requires a report of, "any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident", and in accordance with 10 CFR 21, "Reporting of Defects and Noncompliances", the attached Licensee Event Report LER 89-016 (Revision 01) is hereby submitted. This revision is necessary to correct the event date on page 1.

Due to the date of the original installation (1969), the condition is technically not 10 CFR 21 reportable. However, due to the potential significance of the failure scenario, Rochester Gas & Electric is submitting voluntary notification. information regarding failure identification and corrective actions can be obtained from Mr. Richard A. Baker, Electrical Engineering, on (716) 546-2700.

This event has in no way affected the public's health and safety.

> Very truly yours, Robert C. Mecredy General Manager Nuclear Production

xc: U.S. Nuclear Regulatory Commission

Region I

475 Allendale Road

King of Prussia, PA 19406

Ginna USNRC Senior Resident Inspector

(pt N° 95718| 1828

9002120255 900126 PDR ADOCK 05000244