EAR REGULA

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION V

SUITE 202, WALNUT CREEK PLAZA 1990 N. CALIFORNIA BOULEVARD WALNUT CREEK, CALIFORNIA 94596

MAR 23 1979

Docket No. 50-397

Washington Public Power Supply System P. O. Box 968 Richland, Washington 99352

Attention: Mr. N. O. Strand Managing Director

Gentlemen:

Subject: Report on Deficiency Involving Defective Welds In Pipe Whip Restraint Brackets, WNP No. 2 (your letter of March 13, 1979)

Thank you for your letter, referenced above, which forwarded a report pursuant to 10 CFR 50.55(e) regarding the subject matter.

Your report will be reviewed and evaluated and should we require additional information concerning this matter, we will contact you.

Your cooperation with us is appreciated.

Sincerely,

10th Engells

R. H. Engelken Director

MA

C. FICES

7904300190

.

÷ .

en Solar en 1990 Maria a 1990 Maria a 1990 λ.

• • • •

•

• • • •

OEDOG2